

Feuille1

VG = 0V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,212	0,601	1,104	1,699	2,375	3,122	3,934	4,806	5,735

VG = 0V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	6,717	7,749	8,830	9,956	11,127	12,340	13,594	14,888	16,221	17,592

VG = 0V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	18,998	20,441	21,918	23,430	24,974	26,551	28,160	29,800	31,471	33,172

VG = 0V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	34,902	36,662	38,450	40,267	42,110	43,982	45,880	47,805	49,757	51,733

VG = 0V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	53,736	55,764	57,816	59,893	61,995	64,120	66,269	68,442	70,638	72,857

VG = 0V

VA (V)	500,000
IA (mA)	75,100

Feuille1

VG = -1V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,119	0,463	0,932

VG = -1V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	1,500	2,151	2,876	3,668	4,522	5,433	6,398	7,415	8,480	9,592

VG = -1V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	10,749	11,948	13,190	14,471	15,792	17,150	18,546	19,977	21,443	22,944

VG = -1V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	24,478	26,045	27,643	29,274	30,935	32,626	34,347	36,098	37,877	39,684

VG = -1V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	41,519	43,382	45,272	47,189	491,131	51,100	53,094	55,114	57,159	59,228

VG = -1V

VA (V)	500,000
IA (mA)	61,322

Feuille1

VG = -2V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -2V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,338	0,771	1,309	1,935	2,637	3,408

VG = -2V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	4,243	5,136	6,084	7,085	8,135	9,232	10,375	11,561	12,789	14,058

VG = -2V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	15,366	16,713	18,097	19,517	20,972	22,462	23,985	25,541	27,130	28,750

VG = -2V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	30,402	32,083	33,795	35,536	37,306	39,105	40,931	42,785	44,666	46,574

VG = -2V

VA (V)	500,000
	48,509

Feuille1

VG = -3V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -3V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -3V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,226	0,620	1,127	1,727	2,405	3,155	3,970	4,845	5,776	6,760

VG = -3V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	7,795	8,877	10,005	11,178	12,393	13,649	14,945	16,279	17,651	19,060

VG = -3V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	20,504	21,983	23,495	25,041	26,620	28,230	29,871	31,544	33,246	34,978

VG = -3V

VA (V)	500,000
IA (mA)	36,738

Feuille1

VG = -4V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -4V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -4V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,131	0,481	0,955	1,526

VG = -4V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	2,181	2,909	3,703	4,560	5,473	6,441	7,459	8,527	9,641	10,799

VG = -4V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	12,001	13,244	14,527	15,849	17,210	18,607	20,039	21,507	23,009	24,545

VG = -4V

VA (V)	500,000
	26,113

Feuille1

VG = -5V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -5V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -5V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -5V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	0,000	0,000	0,055	0,354	0,792	1,335	1,964	2,669	3,443	4,280

VG = -5V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	5,176	6,126	7,129	8,181	9,280	10,425	11,613	12,843	14,114	15,424

VG = -5V

VA (V)	500,000
IA (mA)	16,771

Feuille1

VG = -6V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -6V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -6V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -6V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,240

VG = -6V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	0,640	1,151	1,754	2,436	3,189	4,007	4,884	5,817	6,804	7,840

VG = -6V

VA (V)	500,000
	8,924

Feuille1

VG = -7V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -7V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -7V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -7V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -7V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,143	0,499	0,978	1,553	2,211

VG = -7V

VA (V)	500,000
	2,942

Feuille1

VG = -8V

VA (V)	0,000	10,000	20,000	30,000	40,000	50,000	60,000	70,000	80,000	90,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -8V

VA (V)	100,000	110,000	120,000	130,000	140,000	150,000	160,000	170,000	180,000	190,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -8V

VA (V)	200,000	210,000	220,000	230,000	240,000	250,000	260,000	270,000	280,000	290,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -8V

VA (V)	300,000	310,000	320,000	330,000	340,000	350,000	360,000	370,000	380,000	390,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -8V

VA (V)	400,000	410,000	420,000	430,000	440,000	450,000	460,000	470,000	480,000	490,000
IA (mA)	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000	0,000

VG = -8V

VA (V)	500,000
	0,000